




1. Beeping consistantly, no filter bars visible.



2. Locate minus (-) button.



3. Press and hold for 5 seconds.



4. Until you hear a 'beep' and 6 filter bars are visible.

